

A
MAJOR PROJECT REPORT
ON

**“TPM APPROACH FOR ANALYSIS AND REDUCTION IN
ENGINE LEAKAGE FROM STATOR PLATE”**

SUBMITTED IN PARTIAL FULFILLMENT OF THE REQUIREMENT
FOR THE AWARD OF THE DEGREE OF

**MASTER OF TECHNOLOGY
(PRODUCTION & INDUSTRIAL ENGINEERING)**

Submitted by:
ASHISH VASHISTHA
UNIVERSITY ROLL NO: 2K11/PIE/02

Under the esteemed Guidance of:
Dr. QASIM MURTAZA (Associate Professor)
Dr. SAURABH AGGARWAL (Associate Professor)



DEPARTMENT OF MECHANICAL ENGINEERING

DELHI TECHNOLOGICAL UNIVERSITY

BAWANA ROAD, DELHI.

ACKNOWLEDGEMENT

It is distinct pleasure to express my deep sense of gratitude and indebtedness to my supervisor **Dr. QASIM MURTAZA** Professor, **Department of Mechanical Engineering**, Delhi Technological University, (Formerly Delhi College of Engineering), for his invaluable guidance, encouragement and patient reviews. His continuous inspiration only has made me complete this minor project. Without his help and guidance, this minor project would have been impossible. He remained a pillar of help throughout the project.

I am also grateful to Dr. **Saurabh Aggarwal**, **Department of Mechanical Engineering**, for providing the experimental facilities in various labs of the Department.

I express my sincere gratitude to the faculty and non teaching staff of Mechanical engineering department and the library of Delhi Technological University, (Formerly Delhi College of Engineering) for providing the relevant information and help when needed during the course of my project work.

I am also thankful to my classmates and my friends for their unconditional support and motivation during this work.

(ASHISH VASHISTHA)

(2K11/PIE/02)

M.TECH-FINAL YEAR

CERTIFICATE

Dated :

This is to certify that report entitled “**TPM APPROACH FOR ANALYSIS AND REDUCTION IN ENGINE LEAKAGE FROM STATOR PLATE**” by **Mr. Ashish Vashista**, is the requirement of the partial fulfilment for the award of **Degree of Master of Technology (M.Tech) in Production & Industrial Engineering at Delhi Technological University**. This work was completed under our supervision and guidance. He has completed his work with utmost sincerely and diligence. The work embodied in this project has not been submitted for the award of any other degree to the best of my knowledge.

(Supervisor)

Dr. QASIM MURTAZA

(ASSOCIATE PROFESSOR)

(Co-Supervisor)

Dr. SAURABH AGGARWAL

(ASSOCIATE PROFESSOR)

Department of Mechanical Engineering

**Delhi Technological University, (Formerly Delhi College Of
Engineering), Delhi - 110042**

Session 11~13


<u>CONTENTS</u>	<u>PAGES</u>
1. INTRODUCTION	1 - 1
2. TYPE OF MAINTENANCE	2 - 3
3. TPM HISTORY	3 - 3
4. TPM TARGET AND OEE	4 - 6
5. STAGES IN TPM IMPLEMENTATION	6 - 7
6. TPM ORGANISATION STRUCTURE	7 - 7
7. TPM PILLAR	8 - 21
7. DIFFICULTIES FACED IN TPM	21 - 22
8. SELECTION OF THEME	23 - 23
9. MANAGEMENT INDICATOR	24 - 24
10. IDENTIFY THE PROBLEM	25 - 27
11. UNDESTAND CURRENT SITUATION	28 - 28
12. UNDERSTANDING STATOR PLATE LEAK	29 - 30
13. STATIFICATION OF STATOR PLATE	31 - 32
14. ASSEMBLY VIEW AND CONTRIBUTING PARTS	33 - 36
13. ANALYSIS OF STATOR PLATE LEAK FROM ENGINE	37 - 47
14. ROOT CAUSE	48 - 48
15. TARGET SETTING	49 - 49
16. PLAN OF ACTION	50 - 50

17. ANALYSING THE FACTOR	51 - 54
18. DEVELOPING AND IMPLEMENTING COUNTERMEASURE	55 - 63
19. PERCENTAGE IN IMPROVEMENT IN DEFECT	64 - 64
20. ANALYSING THE FACTOR	66 - 73
21. CONFIRMING EFFECTIVENESS	74 - 74
22. STANDARDIZING & ESTABLISHMENT CONTROL	75 - 77
23. COMPANY STANDARD SHEETS	

1. SELECTION OF THEME

SELECTION OF THEME IS BASED ON THE ANNUAL POLICY (2012 ~ 2013) OF HONDA MOTORCYCLE AND SCOOTER INDIA PVT LTD.

AS PER ANNUAL POLICY



1. Boosting Customer satisfaction through robust outflow control system
2. Strengthening system to ensure zero outflow of defects to customer.
3. Strengthening Problem solving using structured 7 step kaizen story approach.
4. Zero Defect activities

Under this policy, department policy developed and after that Department Manager policy will introduced.

MANAGEMENT INDICATOR: DEPARTMENT MANAGER POLICY:

According to this policy:-

Policy Management - Management Indicator Table - SECTION HEAD QA INPLANT (AMT HANSA)																		
P.M. CODE	No.	Management Indicator	Frequency	KPI	QIP	QIR	2017-18	2018-19		Current Status	Current Status	Strategy				Remarks		
								Target	Actual			Target	Actual	Target	Actual		Target	Actual
Area 1 - Production process and introduction of digital for better and continuous to all work activities																		
101	1	Quality of production of finished goods	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
102	2	Quality of production of components	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
Area 2 - Production process, introduction of digital for better and continuous to all work activities																		
103	3	Production process of finished goods	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
104	4	Production process of components	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
Area 3 - Management process of all work activities																		
105	5	Management process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
106	6	Management process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
107	7	Management process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
108	8	Management process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
109	9	Management process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
110	10	Management process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
111	11	Management process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
112	12	Management process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
Area 4 - Production process of all work activities																		
113	13	Production process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
114	14	Production process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
115	15	Production process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
116	16	Production process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
117	17	Production process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
118	18	Production process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
119	19	Production process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
120	20	Production process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
Area 5 - Production process of all work activities																		
121	21	Production process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
122	22	Production process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
123	23	Production process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
124	24	Production process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
125	25	Production process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
126	26	Production process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
127	27	Production process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
128	28	Production process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
129	29	Production process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95
130	30	Production process of all work activities	95	0	0	0	95	95	95	95	95	95	95	95	95	95	95	95

1. Increase engine straight pass.
2. Zero defect machine in zero loss line.
3. Pm analysis project.
4. Kaizen story / IMP projects.
5. Team suggestions
6. Subordinate development.


HMSI QUALITY POLICY : POLICY FOCUSED ON DEFECT REDUCTION BY STRUCTURED 7 STEP KAIZEN STORY APPROACH

1.1 IDENTIFY THE PROBLEM

To identify the problem we take the data of engine straight pass of three months. Before moving forward it is necessary to know the straight pass. yttStraight means the percentage of engine produced without any defect.

Straight pass = No. of defective engine / No of total engine produced * 100 %

Here I am showing the bar graph of 3 months of Engine straight pass.




By this graph we can say that the average engine straight pass for the month of April, may, june is nearby 96 % which is 4 % less than the target i.e 100 %.

Now the defect contribution for this 4 % department wise is given below.

There are total 4 departments who feed the engine assembly and these 4 departments contribute for the engine straight pass.

SECTION WISE CONTRIBUTION FOR (APRIL '12 ~ JUNE '12)



By this graph we can easily identify that the percentage contribution for the 4 % defect section wise are :-

35 % contribution of engine assembly

3.5 % contribution of crank case.


60 % contribution of Supplier (SQA).

1.5 % contribution of cylinder head department

Now we can say that the top 2 contributing department area engine assembly and SQA.

So for selection of theme and identify the problem I am taking engine assembly defect as an

Improvement project which will be a step towards accomplish our company QA policy.



By doing the parato Analysis we have taken top 10 defects and their contribution. Here we found that


The stator plate leakage is the top most defects and having the contribution of 13.59 percent.

By doing this analysis I have selected my theme of this project which is STATOR PLATE LEAKAGE

FROM ENGINE.

2. UNDERSTANDING CURRENT SITUATION AND TARGET SETTING :-

2.1 UNDERSTANDING CURRENT SITUATION:-




Some of the major components of engine assy are given below.

1. Crankcase right
2. Crankcase left
3. Cylinder head
4. Cylinder block
5. ACG (alternative current generator)

ACG consist of 2 parts. One is stator plate and second is flywheel or rotor.

The function of this ACG is to provide the current for spark plug and various electrical circuits. The stator plate is stationary having the coils and rotor or flywheel is rotary.


Now here i am showing the exploded view of engine to clear the component and assembly of engine.



In this exploded view you can easily understand that the assembly of stator plate is on the left crankshaft in left crank case.

This stator plate is fixed with two screws in left crank case on left crankshaft, after that flywheel or rotor is mounted on crankshaft in such a manner so that it can cover the coil.

ENGINE LEAKAGE TESTING MACHINE AND PROCESS :-



After complete assembly of engine , engine is tested, we called it leakage testing.

Leakage testing machine principle is based on the comparison of master engine (Completely OK engine)with the leakage engine.

We insert the air in both the engine at 0.2 bar. Then there is a stabilization time after filling the air.

If there is any leakage in the engine then the air in the master engine travel or moves towards the leakage one. The flow rate of the leakage or we can say that the flow rate of air from master engine to leakage engine is the leakage value.

As per standard the leakage value is 40 cc/min.

There is a provision on the machine that if there is any leakage engine detected than machine will give red light with buzzer.

In the same fashion, if there is any ok engine , machine will give green light with signal as shown in fig

STATIFICATION OF STATOR PLATE LEAKAGE MODEL, LINE, MONTH AND

VENDOR WISE




Fig 1




Fig 2




Fig 3




Fig 4

In first graph, it shows the percentage of stator plate defect in the month of April , May, June 2012. The Average of stator plate defect of these 3 months is 0.38 % in Quarter 1.


In second graph, it shows the stator plate defect of Quarter 1 line wise. In this graph it is very clear that the defect is coming on each line and almost in equal proportion.

Third Graph Shows the stator plate defect vehicle model wise. First one is for shine mode using two different vendors. Nipon and Denso are the two vendors who provides stator plate for the shine model. For shine model 0.41 % contribution of nipon vendor and 0.04% contribution of denso vendor.

The volume of shine model is very high as comparatively then the other 2 models so we are considering only for the shine model.

In the last graph we can see clearly that for particular shine model, 89% leakage contribution is by nipon stator plate and only 11 % contribution is from denso stator plate.

ASSEMBLY VIEW OF STATOR PLATE AREA



CONTRIBUTING PARTS IN STATOR PLATE LEAKAGE :

1. CRANK CASE LEFT (INHOUSE PART)



2. CRANKSHAFT LEFT



3. STATOR PLATE ASSEMBLY (SUPPLIER)



3a. Stator plate




3b. O'Ring



3c. Oil Seal



MECHANISM UNDERSTANDING OF STATOR PLATE LEAKAGE




This figure shows the assembly of stator plate with crankcase and crankshaft including there child parts of stator plate.

Stator plate consisting of three parts : First is O'Ring on the outer side of the stator plate in the groove. Second is the oil seal in the inner dia of stator plate.

This Stator plate rests in the crankcase left with a slightly interference fit. The inner side of the stator plate which is having oil seal slides over the crankshaft.

In the figure. 3a shows the stator plate. 3b shows the o'ring between crankcase and stator plate. 3c shows the oil seal over the crankshaft.

BREAK UP OF 1069 Nos. (0.68%) LEAKGAE ENGINE IN SUPPLIER M/s NIPPON BASED ON SEALING SURFACES




SEALING SURFACES – STATOR PLATE AREA


- A** O ring and LCC interface
- B** Oil seal and crank shaft left interface
- C** Mounting and LCC interface

This fig. shows the sealing surface of stator plate area. There are three points in this figure A, B, C. A represent the sealing surface between O’ring and LCC interface. B represent the sealing surface between oil seal and crankshaft left interface.

C represents the sealing surface between mounting bolt of stator plate and LCC interface.



1. Represent the crankshaft and oil seal interface.
2. Represent the mounting bolt and lcc interface.
3. O'ring and LCC (left crak case) interface.



BREAKUP OF LEAKAGE FROM THE VARIOUS SEALING SURFACE







FROM THE SEALING POINT A 50 % OF LEAKAGE OBSERVED.

FROM THE SEALING POINT B 45 % OF LEAKAGE OBSERVED.

FROM THE SEALING POINT C 05 % OF LEAKAGE OBSERVED.

THIS DATA SHOWS THAT THE MAXIMUM LEAKAGE OBSERVED FROM THE O'RING AND LCC INTERFACE.

Contributing parts for Leakage From Stator Plate Area **Model - Shine :-**

S.No	Parts	Part Supplied from	Remark	
1.	Crank Case Left 	In-house Manufacturing (Receiving From M/c Shop)	Eliminated for Supplier Difference	
2.	Crank Shaft 	In-house Manufacturing (Receiving From M/c Shop)	Eliminated for Supplier Difference	
3.	Stator Plate Assy. 	M/s. Nippon	M/s. Denso	Complete Stator Plate Assembly Supplied
a.)	- Stator Plate 	M/s. Nippon	M/s. Denso	Assembly Child Part
b.)	- Oil Seal 	M/s. Nippon	M/s. Denso	Assembly Child Part
c.)	- O Ring 	M/s. Nippon	M/s. Denso	Assembly Child Part

CHILD PARTS OF STATOR PLATE ASSEMBLY

LCC and Crank Shaft are common parts & Stator Plate Assembly is received from two supplier


Crankcase left and crankshaft left with stator plate are the contributing parts.

There are two suppliers of stator plate: M/s Nippon & M/s Denso.


Crankcase and crankshaft are common parts and manufactured in house.


CONTRIBUTING PARTS FOR LEAKAGE FROM STATOR PLATE ASSEMBLY :



Part	Dimension	Specification	Remarks
Oil Seal	Oil Seal OD	$30/+0.10/+0.30$	①
	Thickness of Oil Seal	5 ± 0.20	②
	Oil Seal ID	17.90 ± 0.30	③
	Inner Dia 1	18.5 ± 0.30	④
	Oil Seal Cut and flashes	Shouldn't have cut and flashes	⑤
	Extra Material in Oil Seal	Shouldn't have Extra material at Oil Seal.	⑥
	Greasing of Oil Seal	Greasing application	⑦




Part	Dimension with tolerance	Specification	Remarks
O Ring	Diameter	107 ± 0.8	①
	Thickness	2 ± 0.07	②
	Parting Lines and Flashes on O ring	Shouldn't have deep parting lines, cut and flashes	③
	Extra Material at O ring	Shouldn't have Extra material at O ring	④
	Oiling of O ring	Oiling application	⑤



Part	Dimension with tolerance	Specification	Remarks
Stator Plate	Mounting Holes(X2)	6.2±0.20	①
	Position of Holes Ø 6.2		②
	Thickness	7.0±0.2	③
	Outer Diameter	115/-0.36/-0.71	④
	O-Ring groove diameter	111.8/-0.2	⑤
	Thread(X2)	M6X1.0	⑥
	Extra material and dust	Shouldn't be available	⑦
	Chamfer	0.5X45°	⑧
	Ø 115 Finish	12.5 Ra	⑨
	Appearance	No dent and damage	⑩






Part	Dimension with tolerance	Specification	Result
CCL	Ø 115	115+0.035	①
	Ovality in Ø 115	0.011	②
	Chamfer	20°	③
	Ø 115 Finish	12.5 Ra	④
	Appearance	No dent and damage	⑤



Part	Dimension with tolerance	Specification
Crank Shaft	Ø19.00	19.00/-0.026/-0.007
	Appearance	No dent and Damage



CONTRIBUTING DIAMETER COMPARISON:




Part	Dimension with tolerance	Specification (Unit-mm)	Contributing Dimension comparison					
			M/s. Nippon(Leaked Engine)			M/s. Nippon(OK Engine)		
Oil Seal 	Oil Seal OD	30/40.10/40.30	30.23	30.19	●	30.21	30.24	●
	Thickness of Oil Seal	5±0.20	5.01	5.02	●	5.09	5.06	●
	Oil Seal ID	17.90±0.30	17.74	17.79	●	17.81	17.84	●
	Inner Dia1	18.5±0.30	18.65	18.64	●	18.69	18.71	●
	Oil Seal Cut and flashes	Shouldn't have cut and flashes	OK	OK	●	OK	OK	●
	Foreign Material in Oil Seal	Shouldn't have Foreign material at Oil Seal.	foreign Mat Available	foreign Mat Available	●	OK	OK	●
	Greasing of oil seal	Should be done	OK	OK	●	OK	OK	●
O ring 	Diameter	107±0.8	107.45	107.52	●	107.39	107.42	●
	Thickness	2±0.07	1.88	1.90	●	1.94	1.95	●
	Parting Lines and Flashes on O Ring	Shouldn't have deep parting lines, cut and flashes	Flashes	Flashes	●	OK	OK	●
	Foreign Material at O ring	Shouldn't have foreign material at O ring	foreign Mat Available	foreign Mat Available	●	OK	OK	●
	Oiling of O Ring	Oiling Should be done	OK	OK	●	OK	OK	●
Crank Shaft 	Diameter	19.00/-0.26/-0.007	18.989	18.987	●	18.987	18.989	●
	Appearance	No dent and Damage	OK	OK	●	OK	OK	●

After doing analysis of all the parameter of oil seal we found Foreign material in and under the oil seal.

In the same way after analyzing the O-ring parameter we found that the Thickness which should be 2(+/- 0.07) actual found 1.88 and 1.90.

Moreover in O-Ring we found flashes on the surface of O-Ring. In O-Ring also there are some foreign material found.

Rest of all the parameter are within the specification.

Part	Dimension with tolerance	Specification (Unit-mm)	Contributing Dimension comparison					
			M/s. Nippon(Leaked Engine)			M/s. Nippon(OK Engine)		
Stator Plate 	Mounting Holes(X2)	6.2±0.20	6.31	6.29	●	6.34	6.30	●
	Position of Holes Ø 6.2		0.06	0.06	●	0.04	0.03	●
	Thickness	7.0±0.2	7.04~7.06	7.06~7.14	●	7.09~7.12	7.08~7.14	●
	Outer Diameter	115/-0.36/-0.71	114.944~ 114.955	114.930~ 114.944	●	14.932~ 14.948	14.934~ 14.949	●
	O-Ring groove diameter	111.8/-0.2	111.640~ 111.650	111.680~ 111.690	●	111.720~ 111.740	111.710~ 111.730	●
	Thread(X2)	M6X1.0	OK	OK	●	OK	OK	●
	Foreign mat. and dust	Shouldn't be available	Foreign mat/Chips	Foreign mat/Chips	●	OK	OK	●
	Stator Plate Chamfer	0.5X45°	OK	OK	●	OK	OK	●
	Ø 115 Finish	12.5 Ra	8.5 Ra	7.2 Ra	●	9.1 Ra	8.6 Ra	●
	Appearance	No dent and damage	OK	OK	●	OK	OK	●
CCL 	Ø 115	115+0.035	115.008	115.007	●	115.009	115.014	●
	Ovality in Ø 115	0.011	0.007	0.006	●	0.007	0.009	●
	Dia 115 Chamfer	20°	OK	OK	●	OK	OK	●
	Ø 19.00	19.000/-0.026/0.007	18.991	18.989	●	18.986	18.987	●
	Ø 115 Finish	12.5 Ra	6.5 Ra	7.2 Ra	●	7.1 Ra	6.9 Ra	●
	Appearance	No dent and damage	OK	OK	●	OK	OK	●
Total 05 parameters were found out of specification								

Out of ten parameter of stator plate, there is only one parameter which is out of specification.

Foreign material and dust found in stator plate

Total five parameters were found out of specification, listed below

1. Foreign material in oil seal.
2. Foreign material in o-ring.
3. Foreign material in stator plate .
4. Flashes in o ring in parting line
5. Thickness of o ring undersize.



STATOR PLATE O RING THICKNESS (t) SAMPLE POPULATION :-

N=30

Supplier : M/s. Nippon

Dim 2.00±0.070

O-Ring thickness (t)



O ring thickness is found lower than LSL



STATOR PLATE O RING GROOVE DIAMETER (d) SAMPLE POPULATION :-

N=30

Supplier : M/s. Nippon

Dim 111.800/-0.200

Stator Plate O ring groove dia(d)



Maintained at Mean






83% of O ring found out of specification and Stator Plate O ring groove dia found with in specification

Now to ensure the o ring thickness we prepared a graph of O ring thickness and take sample population of O'Ring thickness.

By measuring the o ring thickness of 30 nos we observed that out of 30, total 25 o ring diameter are out of specification. Lower than the lower limit.

It means 83% sample population are out of specification.


We also checked the stator plate o ring groove dia by take the sample population of 30 nos. all the 30 nos found within the specification.

S.No	Component name	Characteristics	Specification	Sketch	Observation
1.)	Oil Seal	Contamination	Foreign Material not allowed		Foreign material in oil seal.
2.)	O Ring	Parting lines and Flashes	Deep parting lines and flashes not allowed		Flashes on O ring
3.)	O Ring	Contamination	Foreign material not allowed		Foreign material on O ring
4.)	Stator Plate	Contamination	Foreign material not allowed.		Foreign material /Chips on stator plate O ring groove.
5.)	O Ring	Thickness	2 ± 0.07		Found undersize.

Now there are total 5 parameter on which we have to work.


1. Oil Seal contamination
2. O Ring Parting line and flashes.
3. O Ring Contamination.
4. Stator Plate Contamination
5. O Ring Thickness.

TARGET SETTING:



The current status of Engine leakage is 0.38% which we have to reduce up to 0.05%.

PLAN OF ACTION :




In this I am showing my plan of action. I am doing this in 4 phases.

First one is analyzing the factor, after that developing and implementing countermeasure against the engine leakage.

Then confirm effectiveness. Whatever the countermeasure will be taken to eliminate the engine leakage, we have to check the effective of those countermeasure.

And if those countermeasure are ok to eliminate the engine leakage then we have to standardize those countermeasure in the Standard Operating Procedure.

ANALYSING THE FACTOR :




For the foreign material in oil seal and o ring, we have done why why analysis and found that oil seal and o ring are being assembled in open area, exposed to environmental foreign material.

The second thing is packing bins of stator plate assembly is not being covered.

And the third is operator was not aware about the inspection of foreign material.


As a countermeasure of all these 3 reasons we have started stator plate assembly and inspection in closed chamber. Assembled component started packing in closed plastic bins. Check point for inspection is added in PDI Stage. Relay teaching has been started for the inspection of foreign material.



Foreign Material/Chips on stator plate o ring groove is the another observation. After doing analysis we found that packing bins are not being cleaned regularly. Air cleaning processes doesn't ensures chips free stator plate to the next process.no check point fot the inspection of packed component for foreign material.


As a countermeasure of all these , packing bins cleaning system started after each usage cycle. Compressed air used for cleaning/removal of loose chips on stator plate. Relay teaching has been done for the inspection of foreign material in packing bins at PDI stage.

Why-Why Analysis for O ring thickness less :-

Phenomenon	WHY -1	WHY -2	WHY -3	WHY -4	WHY -5	Countermeasure
O ring thickness less 	Material run radius is less in mould.	Foreign particle sticks on the surface of mould	Mould Cleaning and Polishing is not being done regularly.			- Polishing/Cleaning done and frequency fixed and being adhered.
	O ring thickness inspection was being done after a specified time duration	Mould/Cavity wise inspection was missing				Mould/Cavity , batch wise inspection started.






Process Flow of O Ring (Supplier : M/s. Nippon)



Against the phenomenon of O ring thickness less, when we have done why why analysis, we found that mould cleaning and polishing is not being done regularly. The second thing is Mould/cavity wise inspection was missing. As a countermeasure polishing/cleaning done and frequency of cleaning fixed and being adhered.


Mould /cavity, batch wise inspection started.

Why-Why Analysis for flashes on O ring :-

Phenomenon	WHY -1	WHY -2	WHY -3	WHY -4	WHY -5	Countermeasure
Flashes on O ring. 	Flashes didn't tear off completely.	O ring parting line area thickness is more.	Mould notches worn out.	Notch and tool maintenance frequency not fixed.		Tool notches re-shaped and its maintenance schedule fixed.
	De-flashing was not being done completely	Operator was not able to detect minor flashes by naked eyes.				Magnifying glass provided for the visual inspection of O ring

Why-Why for Generation
Why-Why for Outflow

Process Flow of O Ring (Supplier : M/s. Nippon)




Now we have done why why for flashes on o ring. We found that notch and tool maintenance frequency not fixed. Operator was not able to detected minor flashes by naked eyes.

The first countermeasure is tool notches reshaped and its maintenance schedule fixed.

The second countermeasure is magnifying glass provided for the visual inspection of O'ring.

DEVELOPING AND IMPLEMENTING COUNTERMEASURES :

Countermeasure of foreign material in Oil seal, O ring and Stator Plate : -



By this figure I am trying to show the close chamber of stator plate assembly , due to which o ring, oil seal and stator plate will be free from any type of foreign material.

Countermeasure of foreign material in Oil seal, O ring and Stator Plate :-

Stator plate assembly in dedicated Poly Packed Plastic bins

BEFORE



Packing bins are not Poly Packed

AFTER




Poly Packed Plastic bins

Polythene cover added in Plastic packing bins to avoid foreign material sticking on Stator Plate


This picture shows the poly packed plastic bins to avoid foreign material in o ring, oil seal and stator plate.

Countermeasure of foreign material/chips on stator plate O ring groove :-



This picture shows the packing bin cleaning after each cycle. Flow chart of this process is also shown in this picture. As per flowchart after getting empty bin from vendor, bin has to be cleaned with water before feeding or packing the new stator plate. After washing the bins, stator plate is going to pack in washed bins and then move for dispatch to the customer.

Countermeasure of foreign material/chips on stator plate O ring groove : -



Now as a part of countermeasure of foreign material/chips on stator plate o ring groove we started compressed airspray in the groove so that the possibility of stuck chips inside the o ring will be zero.

OPL and relay teaching done to avoid extra material in Stator Plate Assembly

OPL for inspection of Extra Material

ONE POINT LESSON		DATE: 15.12.21		
OPERATION	Stator coil OD turning	PRODUCTS	STATOR COIL	
FAILURE	ROOT CAUSE	CONTROL METHOD		
1	Chips Problem In ACQ P17	Stator coil not cleaning 100% by brush after OD turning & No cross check available	100% Clean by brush after OD turning	
				
EFFECT ON PRODUCT QUALITY & CUSTOMER USAGE :				
1 - Lowest problem				
CUSTOMER COMPLAINT HISTORY				
S.No	NATURE OF COMPLAINT	APPLICATION	DATE OF COMPLAINT	CORRECTIVE ACTION
1	Found chips in stator coil	P-17 ACQ	08.12.21	100% Clean by brush - Revis in Operator Cross check for Line supervisor
2				
3				
Prepared by :		Approved by :		

Quality Alert Displayed at Bin Cleaning area

QUALITY PROBLEM ALERT		DATE : 24/02/2022
PRODUCT	ICOEEL PLATE	
PART NO/MODEL	N20 49264	
CUSTOMER	INEL REWARI	
CUSTOMER COMPLAINT		
		
CHIPS ON COMPONENT		
<p>•यह ध्यान रखें कि: बिन साफ —सूखी हो। बिन में किसी प्रकार की पिंपा और डस्ट नहीं होना चाहिए।</p>		
		
Bin Cleaning		
PROD. TEAM	INITIATED BY : QA TEAM	

OPL and relay teaching to avoid extra material in Stator Plate Assembly

For the teaching purpose of man we prepared OPL (one point lesson) in which we have shown that what thing a person has to ensure before assembly.

In this OPL person has to ensure the cleaning of chips from stator plate by using brush.

Countermeasure of O ring thickness less :-



Moulding Machine

O Ring Injection Moulding Machine **Polishing/Cleaning and tool notches re-shaped**

ACTIONS :-

1. Flash rest groove cleaned and polished to maintain material run radius.
2. Tool and its notches re-shaped to cut away the flashes from O ring.
3. Batch/Mould/Cavity wise inspection started to monitor the parameters within specifications.



Inspection Process

Injection moulding tool's cleaning and polishing done & Batch/Mould/Cavity wise inspection started.

As a countermeasure of O ring thickness we have started cleaning and polishing of mould to maintain material run radius.

Tool and its notches reshaped to cut away the flashes from O'ring.

Batch/Mould/Cavity wise inspection started to monitor the parameter within the specifications.

Countermeasure of flashes on O ring : -

O Ring- **BEFORE**



O Ring- **AFTER**




FLASHES ON O RING



NO FLASHES ON O RING

Tool maintenance Schedule



Tool ID	Maintenance Type	Start Date	End Date
001	Sharpening	2023-01-01	2023-01-05
002	Inspection	2023-01-05	2023-01-05
003	Sharpening	2023-01-10	2023-01-15
004	Inspection	2023-01-15	2023-01-15
005	Sharpening	2023-01-20	2023-01-25
006	Inspection	2023-01-25	2023-01-25
007	Sharpening	2023-02-01	2023-02-05
008	Inspection	2023-02-05	2023-02-05
009	Sharpening	2023-02-10	2023-02-15
010	Inspection	2023-02-15	2023-02-15

Relay teaching



Tool maintenance schedule has been made and relay teaching done to detect and control the process conditions

Tool Life and its maintenance schedule has been made to control the process condition. In this figure we can easily understand that after sharpening the tool the generation of flashes is completely removed.



Countermeasure of flashes on O ring : -

Visual Inspection of O Ring

Visual inspection of O Ring by Magnifying Glass



Inspection (by Magnifying glass)



Magnifying Glass is being used for the inspection of O ring to increase the detection level


We have started visual inspection of o ring by using magnifying glass to arrest the flashes of o ring.

Summary of Countermeasures for Engine leakage from Stator Plate Area :-


Phenomenon	Root Cause	Countermeasure	Status
Foreign Material on Oil Seal and O ring	Oil seal and O ring are being assembled in open area, exposed to environmental foreign material. Packing bins of Stator Plate Assembly is not being covered properly Operator was not aware about the inspection of foreign material	-Stator Plate Assembly and PDI will now being done in closed chamber -Assembled components would be Packed in dedicated poly pack plastic bins - Check point added in at PDI Stage. - Relay teaching has been done for the inspection of foreign Material.	●
Foreign Material/Chips on Stator Plate O ring groove	Packing bins are not being cleaned regularly. Air cleaning process doesn't ensures chips free Stator plate to the next process No check point for the inspection of Packed components for foreign material	- Packing bins cleaning system started after each usage cycle. -Compressed air cleaning for the removal of loose chips on Stator Plate until the plate is completely cleaned -Check point added. -Relay teaching has been done for the inspection of foreign Material in packing bins at PDI stage.	●
O ring thickness less	Mould Cleaning and Polishing is not being done regularly. Mould/Cavity wise inspection was missing	-Polishing/Cleaning done and frequency fixed and being adhered. -Mould/Cavity , batch wise inspection started.	●
Flashes on O ring.	Notch and tool maintenance frequency not fixed. Operator was not able to detect minor loose flashes by naked eyes.	-Tool notches re-shaped and its maintenance schedule fixed. Magnifying glass provided for the visual inspection of O ring	●

CONFIRMING EFFECTIVENESS:

Effectiveness of : Model Shine – After Implementing the Countermeasures




After taking these countermeasure we achieved 55% of improvement till the end of Dec'12.



Leakage reduced by 55% in model shine after implementing the countermeasure (Dec'12) yet the contribution of Nippon is still 84%.


So further analysis is required to achieve zero defect.

ANALYSING THE FACTOR:



After doing further analysis of total 148 nos of defect, we found that leakage contribution from the sealing surface A is the highest which is 91%. Point C is having 2% of leakage which is from mounting and LCC interface. And 7% leakage is found from oil seal and crankshaft interface.




INVESTIGATE CHARACTERISTICS VALUE AND CURRENT SITUATION:



O ring between stator plate groove and crankcase interface provide sealing in such a manner so that there must be no leakage.


After doing comparison of two vendors Nippon and Denso based on the sample population trend we found that 26% sample population are found between Mean and USL in Nippon supplier.it confirm minimum sealing

In Denso vendor 97% sample population found between mean & USL. It confirm maximum sealing.


Part	Dimension with tolerance	Specification (Unit-mm)	Contributing Dimension comparison in both vendors For sealing Surface (A)								
			M/s. Nippon (Leaked Engine)			M/s. Nippon (OK Engine)			M/s. Denso (OK Engine)		
O ring 	Diameter	107±0.8	107.45	107.52	●	107.44	107.50	●	107.41	107.38	●
	Thickness	2±0.07	1.98	2.01	●	2.01	2.00	●	2.02	2.00	●
Stator Plate 	O-Ring groove diameter	111.8/-0.2	DIFFERENCE IN THE DIMENSION RANGE								
			111.630~ 111.640	111.640~ 111.660	●	111.730~ 111.760	111.740~ 111.770	●	111.740~ 111.750	111.750~ 111.770	●
	Outer Diameter	115/-0.36/-0.71	114.942~ 114.951	114.928~ 114.939	●	114.943~ 114.950	114.927~ 114.937	●	14.942~ 14.949	14.937~ 14.945	●
LCC 	Ø 115	115+0.035	115.008	115.007	●	115.007	115.006	●	115.009	115.014	●
	Ovality in Ø 115	0.011	0.007	0.006	●	0.004	0.008	●	0.007	0.009	●
	Dia 115 Chamfer	20°	OK	OK	●	OK	OK	●	OK	OK	●
All contributing parameters found within specification & the difference observed between the range of Stator Plate O ring Groove Dia. in Leaked and OK engine											

After comparison of Stator plate, o ring and Crankcase dimension we found difference in the dimension of o ring groove. The difference observed between the range of stator plate o ring Groove dia in leaked and OK engine. It is observed that the dimension which is coming out in leakage engine is on the lower side. but in ok engine it is found that the dimension lie between USL and mean.

STATOR PLATE O RING GROOVE DIAMETER (d) SAMPLE POPULATION Dim 111.800/-0.200 N=500x3



STATOR PLATE O RING THICKNESS (t) SAMPLE POPULATION :- Dim 2.00±0.070 N=500x3



No Major Observation in O Ring Thickness in both the supplier
 In Stator Plate O ring Groove Dia. 52% Population of M/s Nippon Lying between Mean & USL


M/s. Nippon (Supplier) visit done to study the capability of machine for Stator Plate O ring groove diameter




M/s. NIPPON – SUPPLIER VISIT



Gauge to check groove dia



111.8-0.2




MOM with Supplier

Stator Plate Groove diameter turning and facing on CNC Machine






Supplier M/s. Nippon is having two production lines in which two CNC turning machines are there, We did the capability study for these machines.


Short Term Process Capability Study of CNC Turning M/C-For Groove diameter 111.80-0.2





Short Term SPC
for continuous
30 Pieces





Short Term SPC
for continuous
500 Pieces



Long Term Process Capability Study of CNC Turning M/C-For Groove diameter 111.80-0.2




Subgroup Size-5
Duration-1 Month
Cp=2.73
Cpk=2.60




Subgroup Size-5
Duration-1 Month
Cp=2.76
Cpk=2.62

Further actions : 3 Lots of 10,000 Pieces was demanded from M/s. Nippon having groove dia between Mean and USL



This trial confirms that keeping Stator Plate O ring groove dia(d) at upper side (between mean and USL) confirms maximum sealing in engine from stator plate area.

CONFIRM EFFECTIVENESS: RESULT CONFIRMATION



STANDARDIZING & ESTABLISHING CONTROL:

Before Countermeasure

Procedure of stator plate fitment is not completely defined SOP

7	Stator plate fitment	Fit stator plate by using oil seal guide	Oil seal guide should be free from crack & Dent	Oil seal Damage
---	----------------------	--	---	-----------------

STANDARD OPERATING PROCEDURE					
STAGE	BAR LINE / SEQ	PRODUCTION LEVEL	100% VIEW/PAFT	MODEL	WORK CENTER / M/C/T/O
1	Oil pouring	Oil is poured into the oil seal	Oil seal should not be damaged	Oil seal damage	
2	Oil ring fitment	Oil ring is fitted into the groove of the stator plate	Oil ring should not be damaged	Oil ring damage	
3	Oil seal fitment	Oil seal is fitted into the groove of the stator plate	Oil seal should not be damaged	Oil seal damage	
4	Oil seal guide fitment	Oil seal guide is fitted into the groove of the stator plate	Oil seal guide should not be damaged	Oil seal guide damage	
5	Stator plate fitment	Stator plate is fitted into the groove of the stator plate	Stator plate should not be damaged	Stator plate damage	
6	Oil seal guide fitment	Oil seal guide is fitted into the groove of the stator plate	Oil seal guide should not be damaged	Oil seal guide damage	
7	Oil seal guide fitment	Oil seal guide is fitted into the groove of the stator plate	Oil seal guide should not be damaged	Oil seal guide damage	

After Countermeasure

Stator Plate fitment procedure is defined in detail, at micro level step.

STANDARD OPERATING PROCEDURE									
STAGE	BAR LINE / SEQ	PRODUCTION LEVEL	100% VIEW/PAFT	MODEL	WORK CENTER / M/C/T/O				
1	Oil pouring	Oil is poured into the oil seal	Oil seal should not be damaged	Oil seal damage					
2	Oil ring fitment	Oil ring is fitted into the groove of the stator plate	Oil ring should not be damaged	Oil ring damage					
3	Oil seal fitment	Oil seal is fitted into the groove of the stator plate	Oil seal should not be damaged	Oil seal damage					
4	Oil seal guide fitment	Oil seal guide is fitted into the groove of the stator plate	Oil seal guide should not be damaged	Oil seal guide damage					
5	Stator plate fitment	Stator plate is fitted into the groove of the stator plate	Stator plate should not be damaged	Stator plate damage					
6	Oil seal guide fitment	Oil seal guide is fitted into the groove of the stator plate	Oil seal guide should not be damaged	Oil seal guide damage					
7	Oil seal guide fitment	Oil seal guide is fitted into the groove of the stator plate	Oil seal guide should not be damaged	Oil seal guide damage					

Detailed micro level SOP with 8 sub steps for stator plate fitment is introduced



Countermeasure conformation and adherence standards :-

Countermeasure conformation Standard updated

Countermeasure conformation check sheet revised

Stator Plate Leakage prevention action monitoring Sheet							Revised By
Engine Assy.							Revision No.
Honda							Effective Date
Model							Page Number
Month							1 of 1
Date							Month
Year							Year
No.	Detail of Check Point	Model	Controlling AI	Why	Verification Method	Controlling Frequency	Remarks
1	Oil Seal Guide should not be cracked	3000 XCR	Process	To avoid oil seal cut	Visual verification	1 Per Shift	
2	Oil Seal Guide must be used 100%	3000 XCR	Process	To avoid taper flange	Visual verification	1 Per Shift	
3	Alignment Pin should not bend and damage	All Models	Process	To avoid taper flange	Visual verification	1 Per Shift	
4	Alignment Pin must be used 100%	All Models	Process	To avoid taper flange	Visual verification	1 Per Shift	
5	Oil PROTECTIVE extra plate should be placed on Protractor in master conveyor	XCR	Process	To avoid extra material adhesion on Plate from master conveyor	Visual verification	1 Per Shift	
6	3000 Stator Plate should be placed UP side assy (not touch to the Master conveyor)	3000	Process	To avoid extra material adhesion on Plate from master conveyor	Visual verification	1 Per Shift	
7	Tighten the screw (Torque) by 1-1.1 method of tightening	All Models	Process	To avoid taper flange and torque loss of stator plate	Visual verification	1 Per Shift	
8	Extra Material should not be in Stator Plate at in ring groove and Oil Seal	All Models	Input	To avoid extra material adhesion on Plate from input	Visual verification	1 Per Shift	
9	Deep Parting Line, Flange and Deep cut should not be on O-ring	All Models	Input	To avoid leakage	Visual verification	1 Per Shift	
10	Oil Seal Cut should not be cut	All Models	Input	To avoid leakage	Visual verification	1 Per Shift	
11	Oil Seal sequence must be followed	All Models	Process	To avoid leakage	Visual verification	1 Per Shift	
Prepared By Sachin K. Sharma							Approved By Anil Hande

Stator Plate Leakage prevention action monitoring Sheet							Revised By
Engine Assy.							Revision No.
Honda							Effective Date
Model							Page Number
Month							1 of 1
Date							Month
Year							Year
No.	Detail of Check Point	Model	Controlling AI	Why	Verification Method	Controlling Frequency	Remarks
1	Oil Seal Guide should not be cracked	3000 XCR	Process	To avoid oil seal cut	Visual verification	1 Per Shift	
2	Oil Seal Guide must be used 100%	3000 XCR	Process	To avoid taper flange	Visual verification	1 Per Shift	
3	Alignment Pin should not bend and damage	All Models	Process	To avoid taper flange	Visual verification	1 Per Shift	
4	Alignment Pin must be used 100%	All Models	Process	To avoid taper flange	Visual verification	1 Per Shift	
5	Oil PROTECTIVE extra plate should be placed on Protractor in master conveyor	XCR	Process	To avoid extra material adhesion on Plate from master conveyor	Visual verification	1 Per Shift	
6	3000 Stator Plate should be placed UP side assy (not touch to the Master conveyor)	3000	Process	To avoid extra material adhesion on Plate from master conveyor	Visual verification	1 Per Shift	
7	Tighten the screw (Torque) by 1-1.1 method of tightening	All Models	Process	To avoid taper flange and torque loss of stator plate	Visual verification	1 Per Shift	
8	Extra Material should not be in Stator Plate at in ring groove and Oil Seal	All Models	Input	To avoid extra material adhesion on Plate from input	Visual verification	1 Per Shift	
9	Deep Parting Line, Flange and Deep cut should not be on O-ring	All Models	Input	To avoid leakage	Visual verification	1 Per Shift	
10	Oil Seal Cut should not be cut	All Models	Input	To avoid leakage	Visual verification	1 Per Shift	
11	Oil Seal sequence must be followed	All Models	Process	To avoid leakage	Visual verification	1 Per Shift	
Prepared By Sachin K. Sharma							Approved By Anil Hande

✓ - WORKING ✗ - NOT WORKING

Countermeasure conformation and adherence standards :-

One Point Lesson

ONE POINT LESSON				
OPERATION: Stator coil CO turning		PRODUCTS: STATOR COIL		
FAILURE	ROOT CAUSE	CONTROL METHOD		
1. Chips Problem In ACQ P17	Stator coil not cleaning 100% by brush after CO turning & No cross check available	100% Clean to mark after CO turning		
				
EFFECT ON PRODUCT QUALITY & CUSTOMER USAGE :-				
1. Filtered problem				
CUSTOMER COMPLAINT HISTORY				
S.No	NATURE OF COMPLAINT	APPLICATION	DATE OF COMPLAINT	CORRECTIVE ACTION
1	Found chips in stator coil	P-17 ACQ	08.11.11	100% Clean to mark Make in Operator Cross Check by Line supervisor
2				
3				
Prepared by : _____		Approved by : _____		

Tool Maintenance Schedule

WORLD COMPLETION SCHEDULE FOR THE YEAR 2011 - 2012											
Sl.No	Tool Name	Location	Category	Year	Month	Day	Time	Person	Status	Remarks	Remarks
1	Stator coil	Stator coil	Stator coil	2011	08	11	10:00	Operator	Completed		
2	Stator coil	Stator coil	Stator coil	2011	09	15	10:00	Operator	Completed		
3	Stator coil	Stator coil	Stator coil	2011	10	20	10:00	Operator	Completed		
4	Stator coil	Stator coil	Stator coil	2011	11	25	10:00	Operator	Completed		
5	Stator coil	Stator coil	Stator coil	2011	12	30	10:00	Operator	Completed		
6	Stator coil	Stator coil	Stator coil	2012	01	05	10:00	Operator	Completed		
7	Stator coil	Stator coil	Stator coil	2012	02	10	10:00	Operator	Completed		
8	Stator coil	Stator coil	Stator coil	2012	03	15	10:00	Operator	Completed		
9	Stator coil	Stator coil	Stator coil	2012	04	20	10:00	Operator	Completed		
10	Stator coil	Stator coil	Stator coil	2012	05	25	10:00	Operator	Completed		
11	Stator coil	Stator coil	Stator coil	2012	06	30	10:00	Operator	Completed		
12	Stator coil	Stator coil	Stator coil	2012	07	05	10:00	Operator	Completed		
13	Stator coil	Stator coil	Stator coil	2012	08	10	10:00	Operator	Completed		
14	Stator coil	Stator coil	Stator coil	2012	09	15	10:00	Operator	Completed		
15	Stator coil	Stator coil	Stator coil	2012	10	20	10:00	Operator	Completed		
16	Stator coil	Stator coil	Stator coil	2012	11	25	10:00	Operator	Completed		
17	Stator coil	Stator coil	Stator coil	2012	12	30	10:00	Operator	Completed		
18	Stator coil	Stator coil	Stator coil	2013	01	05	10:00	Operator	Completed		
19	Stator coil	Stator coil	Stator coil	2013	02	10	10:00	Operator	Completed		
20	Stator coil	Stator coil	Stator coil	2013	03	15	10:00	Operator	Completed		
21	Stator coil	Stator coil	Stator coil	2013	04	20	10:00	Operator	Completed		
22	Stator coil	Stator coil	Stator coil	2013	05	25	10:00	Operator	Completed		
23	Stator coil	Stator coil	Stator coil	2013	06	30	10:00	Operator	Completed		
24	Stator coil	Stator coil	Stator coil	2013	07	05	10:00	Operator	Completed		
25	Stator coil	Stator coil	Stator coil	2013	08	10	10:00	Operator	Completed		
26	Stator coil	Stator coil	Stator coil	2013	09	15	10:00	Operator	Completed		
27	Stator coil	Stator coil	Stator coil	2013	10	20	10:00	Operator	Completed		
28	Stator coil	Stator coil	Stator coil	2013	11	25	10:00	Operator	Completed		
29	Stator coil	Stator coil	Stator coil	2013	12	30	10:00	Operator	Completed		
30	Stator coil	Stator coil	Stator coil	2014	01	05	10:00	Operator	Completed		